

	JFM Engineering, Inc.		<i>28 July 2016</i>
	Product Technical Bulletin		TB1603
Products Affected			
Product	Model	SN	NOTES
MasterCharger	ALL	---	---
Superseder II	ALL	---	---
Superseder III	ALL	---	---
Replacement of Current Selector Pots With New Assembly Due to the Discontinuation of the Bourns CT26 Dial.			

1.0 Introduction

- Due to the discontinuation of the Bourns CT26 dial, JFM Engineering is making a new current selectors plate assembly available to retrofit or repair units equipped with the Bourns CT26 dials. This new assembly can be installed over the portion of the front panel that previously housed the CT26 dials. Contact JFM Engineering for pricing and availability.

2.0 Overview

2.1 P/N 9811960210

2.2 JFM Part Data Sheet

- http://www.jfmeng.com/part_data_sheets/9811960210.pdf

2.3 Installation Notes

- Retrofitting requires that two holes be drilled into the front panel of the unit.